


# Explosive drawing LP901



## Part list:

- 1. Temperature limiter
- 2. Indicator light
- 3. Thermostat
- 4. Electric Body Assembly
- 5. Cable
- 6. Body Assembly
- 7. Pan
- 8. Basket
- 9. Lid